



Boletim Especial de Aeronavegabilidade (*Special Airworthiness Bulletin*)

ATA: 73 Engine – Fuel and Control

BEA Nº 2020-04

Date: May 07th 2020

Subject: Suspected Unapproved Parts

Introduction

This Special Airworthiness Bulletin (BEA) advises you, owners, operators and maintenance organizations, about suspected unapproved parts

Background

On April 30th 2020, ANAC was informed by B.G.&P TAXI AÉREO E SERVIÇOS AERONÁUTICOS LTDA – CHOPPER SOLUTION that the following parts manufactured by TURBOMECA were lost and they might have been used in the aviation industry without a due reliable origin and traceability:

Part Number (P/N)	Name	Serial Number (S/N)
0164548250	Adjusted Control Unit	40010
0174078030	Complete Valve	1142
0174126090	Overspeed Bleeding Valve	1673

Recommendation

Once they are suspected unapproved parts and, consequently, do not have an approval for return to service that certifies their airworthiness, ANAC recommends to the owners, operators and maintenance organizations the inspection of their aircraft regarding the installation of the parts described above. If one of these parts is installed, replace it with a new or used one before the next flight. The used parts shall have the records required by Regulamento Brasileiro de Aviação Civil (RBAC 43.9) for approval for return to service.

Note: The verification of the applicable maintenance records can be used instead of the inspection if it is possible to determine, following these records, that the parts are not installed.

For information, contact

Agência Nacional de Aviação Civil (ANAC)
Gerência Geral de Certificação de Produto Aeronáutico (GGCP)
Rua Laurent Martins, 209, Jardim Esplanada II
12242-431 – São José dos Campos – SP.
Telefone: (12) 3203-6660
E-mail: pac@anac.gov.br