

Produtos e modelos habilitados à fruição dos benefícios fiscais da Lei de Informática

Nome Fantasia:	LG ELECTRONICS
Razão Social:	LG ELECTRONICS DO BRASIL LTDA
CNPJ:	01.166.372/0001-55
Endereço:	Av. Dom Pedro I, 7777 Piracangagua II Taubaté / SP - 12.091-000
Contato:	YUN HWAN RHO mct-lge@lge.com (11)22025107 http://www.lg.com/br

Produto:	Aparelho emissor com receptor incorporado, digital, com tela sensível ao toque, próprio para uso como interface de terminal portátil de telefonia celular
Processo MCT/Data:	01200.001868/2014-47 de 02/05/2014
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	96, de 27/02/2015 DOU 02/03/2015 ()
Modelos:	(10-03-15: LG-W110) (10-03-15: LG-W100) (01-04-15: LG-W150) (15-06-15: LGW150)

Produto:	Máquina Automática para Processamento de Dados, Digital, Portátil de peso inferior a 3,5Kg, com teclado alfanumérico de no mínimo 70 teclas e com uma tela (écran) de área superior a 140 cm2 e Inferior a 560cm2
Processo MCT/Data:	01200.000777/2006-84 de 03/03/2006
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	471, de 26/07/2006 DOU 28/07/2006 ()
Modelos:	LW40; LW45; LE55; RA400-5; (24-06-08: E200-A)(31-10-08: X110-L)(31-10-08: X110-G)(11-02-09: E210-M)(19-05-09: X120-L)(19-05-09: X120-G)(27-08-09: X130-L)(27-08-09: R480-L)(27-08-09: R480-G)(27-08-09: X130-G)(31-08-09: TESTE 31/08)(13-01-10: R380-A)(11-02-10: R490-G)(06-05-10: X200-L)(06-05-10: R460-L)(20-05-10: X140-L)(20-05-10: X140-G)(21-06-10: X140-A)(25-06-10: R490-K)(10-11-10: A410-G) (06-12-10: A410-K) (08-12-10: C400-G) (01-04-11: X170-L) (01-04-11: X170-G) (01-04-11: X170-D) (01-04-11: P420-G) (01-04-11: P420-K) (08-07-11: P430-G) (08-07-11: P430-K) (03-10-11: S425-G) (03-10-11: S425-C) (03-10-11: S425-L) (03-10-11: S425-A) (26-01-12: S430-G) (09-02-12: Z330-G) (30-03-12: Z430-G) (25-06-12: N450-S) (25-06-12: N450-P) (30-08-12: Z355-G) (30-08-12: Z460-G) (21-10-12: N460-S) (21-10-12: N460-S) (21-10-12: N460-S) (21-10-12: N460-S) (21-10-12: N460-P) (19-11-12: S460-G) (19-11-12: S460-L) (17-12-12: U460-G) (26-12-12: H160-G) (05-06-13: Z360-G)(22-11-13: 11T540-G) (19-02-14: 13Z940-G) (29-07-14: 10T550-G)(19-02-15: 14Z950-G) (22-07-15: 14U360-L) (07-12-16: 15U470-G) (07-12-16: 15Z970-E) (26-01-18: 14Z980-G) (26-01-18: 15Z980-G) (22-02-18: 14U380-L)

Produto:	Máquina Automática para Processamento de Dados, Digital, Portátil de peso inferior a 3,5Kg, com teclado alfanumérico de no mínimo 70 teclas e com uma tela (écran) de área superior a 560 cm2
Processo MCT/Data:	01200.000777/2006-84 de 03/03/2006
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	471, de 26/07/2006 DOU 28/07/2006 ()
Modelos:	LS70; LS50; LE50; LE55; V1; R400; R405-A (22/11/07); R405-A (03/12/2007,(24-06-08: E500-L)(24-06-08: E500-K) (11-12-08: R510-K)(11-12-08: R410-L)(11-12-08: R510-L)(11-12-08: R410-G)(27-08-09: R580-G)(27-08-09: R580-K) (27-08-09: R580-U)(27-08-09: R580-L)(11-02-10: R590-G)(11-02-10: R590-P)(11-02-10: R590-K)(11-02-10: R590-U) (20-04-10: R580-E)(25-06-10: R590-T)(06-12-10: A510-G) (08-12-10: A510-K) (08-12-10: A510-P) (08-12-10: A510-T) (08-12-10: A510-U) (01-04-11: A520-T) (01-04-11: A520-G) (01-04-11: A520-K) (01-04-11: A520-P) (01-04-11: A520-U) (03-10-11: S525-C) (06-12-11: A530-U) (06-12-11: A530-T) (24-01-12: A520-N) (12-06-12: A550-T) (12-06-12: A550-C) (08-10-12: A560-T) (21-10-12: A560-C) (17-12-12: U560-G) (17-12-12: U560-K)(25-04-14: 15U340-L) (31-10-14: 15U530-G)(22-02-18: 15Z980-G) (22-02-18: 15Z970-E) (22-02-18: 15U470-G) (18-07-19: 17Z990-V)

Produto:	Microcomputador portátil, sem teclado, com tela sensível ao toque ("touch screen"), de peso inferior a 750g (Tablet PC)
Processo MCT/Data:	01200.000469/2011-16 de 28/02/2011
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	681, de 31/08/2011 DOU 01/09/2011 ()
Modelos:	LG-V901(23-10-13: LG-V500) (23-05-14: LG-V400) (23-05-14: LG-V700)(03-07-14: LG-V480) (02-09-14: LG-V490)
Produto:	Modem, para tecnologia celular
Processo MCT/Data:	01200.003497/2008-90 de 11/09/2008
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	289, de 04/05/2009 DOU 05/05/2009 ()
Modelos:	LHU-2100T
Produto:	Terminal fixo de telefonia celular
Processo MCT/Data:	01200.003908/2001-71 de 30/07/2001
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	769, de 13/12/2001 DOU 14/12/2001 ()
Modelos:	LST-2200; LST-2200(F); LST-2300; LST-2300(F); LST-2400; LST-2400(F); LSP-2200; LSP-2200(F); LSP-2300; LSP-2300(F); LSP-2400; LSP-2400(F); LSI-1000; LSI-1100; LPS-2000(27-04-17: LG H870)
Produto:	Terminal portátil de telefonia celular
Processo MCT/Data:	01200.003908/2001-71 de 30/07/2001
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	769, de 13/12/2001 DOU 14/12/2001 ()

Modelos:	LGC-320W; LGC-330W; LGC-500W; LGC-530W; LG-DM110; LG-DM110(I); LG-DM112; LG-DM114; LG-DM115; LG-DM120; LG-DM150; LG-DM510; LG-DM515; LG-DM520; LG-SP110; LG-SP510; LG-DB210; LG-TM210; LG-TM910; LG-BD4000; LG-TM520; LG-DM160; LG-SP110C; LG-LP1000; BD2030; LG-BD670; LG-BX5450; LGG1500; LGG3100; LGG5300/I; LGG5400; LGG5500; LGG7050; LGG7100; LG-BD2233; LG-BX4170; LG-BX6170; LG-C1100; LG-BX7000; LG-BD5130; LG-MX200; LG-MD2330; LG-MG191B; LG-MG200C; LG-MG105; LG-MX500; LG-MD5330; LG-ME500; LG-ME500C; LG-ME540; LGME540C; LG-MX510; LG-MG155; MX800; MW560; MX630; MX240; MX210; MD180; MD2630; MG810C; MG220C; MG210C; MG185C; MG180; MG180C; MG181; MG181C; LG-MD185 MG100C; MG120B; MG320C; MG110C; MD120; ME600C; MG230C; MG125A; MG320D; MG125B; MG225D; MG230D; MG160A; MG280D; ME970C; ME970D; ME550C; ME550D; MG160B; MG280C; MG295D; MG296D; MG296C; MG370A; MG370B MG140A; MG140B; ME850C; ME850D; ME770C; ME770D; MG235C; MU550; MU500; MG375A E MG375B; KP215B; (07/12/2007); KP215A; (07/12/2007); KF600C; (07/12/2007); KF600D; (07/12/2007); KM500C; (07/12/2007); KM500D; (07/12/2007); KP106B; (07/12/2007) KP110A; (07/12/2007); MS25; MS20; KP210 E KP105A.(20-12-07: KF245C)(20-12-07: KF240C)(20-12-07: KE990D) (20-12-07: KE990C)(20-12-07: KF510C)(20-12-07: KF510D)(23-01-08: KF240D)(01-02-08: KM710C)(01-02-08: KM710D)(13-03-08: KF300C)(13-03-08: KF300D)(23-04-08: KF755C)(23-04-08: KP130B)(23-04-08: KF755D)(23-04-08: KP130A)(23-05-08: KM386C)(23-05-08: KM385D)(23-05-08: KM380C)(25-06-08: KF390Q)(25-06-08: KP150Q) (25-06-08: KP265D)(25-06-08: KP260C)(25-06-08: KP265C)(25-06-08: KP151Q)(25-06-08: KF700Q)(25-06-08: KP152Q)(02-10-08: KP570Q)(02-10-08: KC910Q)(02-10-08: KF275D)(08-12-08: GB107B)(08-12-08: KP275C)(08-12-08: KP275D)(11-12-08: GB107A)(22-12-08: GB125B)(22-12-08: GB125A)(22-12-08: GT810H)(17-01-09: KB775F)(11-02-09: GM310F)(11-02-09: KP330F)(11-02-09: GM210)(11-02-09: GD330)(19-02-09: GM205)(27-02-09: KM900F)(24-03-09: GT360)(07-05-09: KP109A)(07-05-09: KP109B)(13-05-09: GM630)(02-07-09: MG377A)(02-07-09: MG377B)(09-07-09: GB230)(10-07-09: GM730F)(27-08-09: GB190A)(27-08-09: GB190B)(27-08-09: GW525F)(27-08-09: GW550H) (22/09/2009 GD900F) (22/09/2009 BL40F) (22/09/2009 GU230) (22-09-2009: GU230) (22-09-2009: GD900F) (22-09-2009: GD900F) (22-09-2009: GD900F) (22-09-2009: BL40F) (22-09-2009: GD900F) (22-09-2009: GD900F) (22-09-2009: GD900F)(12-11-09: GW620F) (22-09-2009: GD900F)(09-12-09: GM750H)(09-12-09: GU285F)(09-12-09: GD510)(18-12-09: GX200)(18-12-09: GM750Q)(18-12-09: GB280)(11-02-10: GS107A)(11-02-10: GS107B)(11-02-10: GD350)(02-03-10: GM600)(16-03-10: GS155A)(16-03-10: GS155B)(24-03-10: GS290)(30-03-10: GX500)(06-05-10: BL20CF)(06-05-10: GT350)(06-05-10: BL20DF)(14-05-10: GU200A)(14-05-10: GU200B)(20-05-10: GT540F)(20-05-10: GM360)(21-06-10: GD880F)(05-08-10: LG-T300)(05-08-10: LG-T310)(17-08-10: LG-A130) (28-09-10: LG-C310) (08-10-10: LG-C105) (08-10-10: LG-C300) (11-10-10: LG-C570F) (15-10-10: LG-P500H) (28-10-10: LG-X335) (30-12-10: LG-P525) (25-02-11: LG-P350F) (25-02-11: LG-A175A) (25-02-11: LG-A175B) (25-02-11: LG-A180A) (25-02-11: LG-A180B) (01-04-11: LG-T500) (01-04-11: LG-E300) (26-04-11: LG-P970H) (06-05-11: LG-V909) (27-05-11: GU295F) (16-06-11: LG-P920H) (16-06-11: LG-P990H) (30-06-11: LG-A190B) (30-06-11: LG-A210A) (30-06-11: LG-A210B) (30-06-11: LG-A230) (15-07-11: LG-C660H) (15-07-11: LG-C600H) (14-09-11: LG-X350) (14-09-11: LG-T515) (14-09-11: LG-E510F) (14-09-11: LG-C375) (14-09-11: LG-C365) (14-09-11: LG-P698F) (14-09-11: LG-T515DW) (06-12-11: LG-A290) (02-03-12: LG-E400F) (30-03-12: LG-P720H) (30-03-12: LG-P705F) (30-03-12: LG-A275) (30-03-12: LG-A270) (02-05-12: LG-T375) (02-05-12: LG-E405F) (24-05-12: LG-C199) (24-05-12: LG-C195) (01-06-12: LG-P940H) (01-06-12: LG-P880) (11-06-12: LG-E612F) (11-06-12: LG-E615F) (20-07-12: LG-T385) (20-07-12: LG-T385) (20-07-12: LG-T385) (20-07-12: LG-T385) (02-08-12: LG-C333) (06-09-12: PG-P768F) (06-09-12: LG-P768F) (14-12-12: LG-E960) (05-02-13: LG-E455F) (05-02-13: LG-E435F) (05-02-13: LG-P716) (05-02-13: LG-E450F) (06-02-13: LG-E977) (27-02-13: LG-E425F) (20-03-13: LG-A395) (20-03-13: LG-P714) (20-03-13: LG-P714) (20-03-13: LG-P714P) (09-04-13: LG-C397) (26-04-13: LG-P875H) (06-05-13: LG-C398) (27-05-13: LG-E470F) (27-05-13: LG-E467F) (29-05-13: LG-E415F) (05-06-13: LG-E989) (18-07-13: LG-E410F) (09-08-13: LG-P655H) (09-08-13: LG-C299) (09-08-13: LG-E465F) (26-08-13: LG-E475F) (26-08-13: LG-D685)(23-09-13: LG-D300F) (23-09-13: LG_D805) (17-10-13: LG-D683) (17-12-13: LG-D821) (30-12-13: LG-D175F) (30-12-13: LG-D956) (03-02-14: LG-D410HN) (03-02-14: LG-D325F8) (14-03-14: LG-D157F) (14-03-14: LG-D285F) (14-03-14: LG-D618) (14-03-14: LG-D180F) (14-03-14: LG-D385) (14-03-14: LGD165F) (04-04-14: LG-D340F8) (25-04-14: LG-D375) (25-04-14: LG-D153F) (13-05-14: LG-D625) (13-05-14: LG-D855P) (23-05-14: LG-D125F) (23-05-14: LG-D127F) (23-05-14: LG-D227) (05-06-14: LG-D105F) (05-06-14: LG-D107F) (05-06-14: LG-D228) (05-06-14: LG-D100F)(01-07-14: LGD855P) (03-07-14: LG-D337) (03-07-14: LG-D724) (03-07-14: LG-D690N) (10-07-14: LG-D295F) (12-08-14: LG-B220)(28-08-14: LG-B525) (29-08-14: LG-D392D)(24-12-14: LG-H422TV) (08-01-15: LGH326TV) (05-02-15: LG-H955A) (05-02-15: LG-H422) (06-02-15: LG-H222TTV) (06-02-15: LG-H442F) (06-02-15: LG-D390) (19-02-15: LG-H502TV) (26-02-15: LG-H502F) (26-02-15: LG-H326T) (26-02-15: LG-H222F) (10-03-15: LG-H522F) (10-03-15: LG-H342F) (24-04-15: LG-H342FT) (24-04-15: LG-H815P) (24-04-15: LG-H818P) (25-05-15: LG-H540T) (25-05-15: LG-H630) (03-06-15: LG-H736P) (30-06-15: LG-H221F) (30-06-15: LG-H340F) (30-06-15: LG-H221F) (30-06-15: LG-H340F) (03-07-15: LG-H520F) (12-11-15: LGK430DSA) (12-11-15: LGK430DSF) (12-11-15: LGK430TV) (12-11-15: LGK130F) (27-11-15: LGK350DS) (18-03-16: LGK500DSF) (18-03-16: LGH840) (25-04-16: LGK430F) (25-04-16: LGK120FT) (13-05-16: LG-H840) (17-06-16: LG-K580DSF) (17-06-16: LGK220DSF) (17-06-16: LG-K200DSF) (07-12-16: LGM250DS) (07-12-16: LG-X230DS) (25-01-17: LGM400DF) (25-01-17: LGM320TV) (03-03-17: LGH870) (26-06-17: LGM700TV) (11-10-17: LG-H870I) (11-10-17: LG-X230DSV) (26-01-18: LM-X210BMW) (21-03-18: LMX410BTW) (21-03-18: LMQ610BA) (21-03-18: LMX410BCW) (26-04-18: LM Q710BAW) (27-04-18: LM-G710EMW) (18-05-18: LM-V350EAW) (07-12-18: LM-X420BMW) (21-03-19: LM-X520BMW) (29-03-19: LM-X525BAW) (29-03-19: LM-G810EAW) (12-06-19: LM-X120BMW) (18-07-19: LM-G850EMW) (18-07-19: LM-X540BMW) (18-07-19: LM-X430BMW)
Produto:	Unidade de disco para gravação de dados por meio óptico
Processo MCT/Data:	01200.004063/2002-11 de 29/07/2002
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	821, de 17/12/2002 DOU 18/12/2002 ()
Modelos:	GCE-8400B; GCE-8525B; GCE-8526B

Produto:	Unidade de disco para leitura de dados por meio óptico
Processo MCT/Data:	01200.001205/2002-99 de 20/03/2002
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	357, de 29/05/2002 DOU 03/06/2002 ()
Modelos:	CRD-8520B; CRD-8521B; GCR 8521B; GCR-8523B; GCR-8483B
Produto:	Unidade de processamento de pequena capacidade, baseada em microprocessador, com unidade de saída por vídeo incorporada ("All in One")
Processo MCT/Data:	01200.000458/2013-06 de 21/02/2013
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	2, de 02/01/2014 DOU 03/01/2014 ()
Modelos:	(03-02-14: V325-M)(27-07-17: 24V570-G) (11-12-17: 22V280-L)
Produto:	Unidade de processamento digital de pequena capacidade, baseada em microprocessadores
Processo MCT/Data:	01200.003908/2001-71 de 30/07/2001
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	769, de 13/12/2001 DOU 14/12/2001 ()
Modelos:	TW15AM016; TW17AM32; TW563A; TW516B; TW517B; TW775B
Produto:	Unidade de processamento digital, de pequena capacidade, baseada em microprocessador, com unidade de saída por vídeo incorporada
Processo MCT/Data:	01200.001789/2012-74 de 04/06/2012
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	71, de 28/01/2013 DOU 29/01/2013 ()
Modelos:	(06-02-13: V320-M) (25-04-13: V720-M) (02-07-13: V960-G)(22-11-13: 22V240-L) (14-03-14: 27V745-G) (14-03-14: 23V545-G) (15-10-14: 23V545-G) (24-10-14: 24V550-G) (24-10-14: 27V750-G) (01-04-15: 29V950-G) (24-08-15: 24V360-L) (22-09-16: 22V270-L) (22-09-16: 24V570-G) (27-10-16: 24V570-E) (27-10-16: 24V570-C) (07-12-16: 24V575-G) (18-05-18: 27V790-C) (28-01-19: 24CK550N-3A) (28-01-19: 24CK550W-3A)
Produto:	Unidade de saída por vídeo (monitor) com tubo de raios catódicos, policromática
Processo MCT/Data:	01200.003908/2001-71 de 30/07/2001
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	769, de 13/12/2001 DOU 14/12/2001 ()
Modelos:	Monitores de 14: SW 1470(CH482); SW44i (CB440; SW440; SW441); SW44M; SW45i; SW45i; (SW485/CS485); Monitores de 15": SW 55i (CS546); SW55i (SW545/CS545); SW57i (CS590); SW1528N (SW560A); SW561B; SW575N; EV575; SW560N; SW561N SW520N; SW521N; CS521); SW57M; SW576B; SW1528S (SW550M); SW5Di; SW5Ei; Monitores de 17": SW77i (CS780; SW780; SW7Di); SW1728N (SW775C; SW775N); SW77M; SW7Ei; SW776B; SW1724N (SW795B-FB795; SW795B-FB795FT; SW795FT-795FTPLUS); Studioworks 500G; Studioworks 500E; Studioworks 561A; Studioworks 563N; Studioworks 563A; SW563A; SW563N; IBM E52(6633-4LE); Studioworks 550A; SW550A; Studioworks 550M; SW550M; COMPAQ MV 540; HP 55 (D8895A); Studioworks 501E; Studioworks 501S; Studioworks 500ME; Studioworks 500M; 700S; IBM E74 (6332-4LE); Studioworks 700S; Studioworks 700M; COMPAQ FS740; flatron E701S; flatron 775FT; flatron F700P; 795FT; Studioworks 995E; Monitores de 17": Studioworks 700E; 700E; E701S; 500ME; Studioworks 502E; Studioworks 502G; SW500E; SW500G; SW561A; 500M; SW700M; F700P; T910B; IBM E50; F700P; F700PJ; Flatron T710BH; Flatron T710SH; StudioWorks 710E; StudioWorks 710S; StudioWorks 710B; StudioWorks 505G; StudioWorks 505GK; StudioWorks 505E; StudioWorks 505 EK; T530B; T530S; FLATRONez T930B; FLATRONez T930BK; FLATRONez T730PH; FLATRONez T730PHK; FLATRONez T730BH; FLATRONez T730SH; FLATRONez T730BHK; FLATRONez T730SHK; FLATRONez T930BU; FLATRONez T930BUK; FLATRONez T530BS; FLATRONez T530BAK; FLATRONez T530SS; FLATRONez T530SAK; E50 (monitor 15?); 74 (monitor 17?); FLATRONez T70PHP; FLATRONez T730PHPK; FLATRONez T710SHP; FLATRONez T710SHPK; FLATRONez T730BHP; FLATRONez T730SHP; FLATRONez T730BHPK; FLATRONez T730SHPK; T710SH plus; T730SH plus; T70B-BN; T70B-SN; T70B
Produto:	Unidade de saída por vídeo (monitor) com visor de cristal líquido, policromática

Processo MCT/Data:	01200.003908/2001-71 de 30/07/2001
CNPJ da Incentivada:	01166372000155
Portaria MCT/MDIC/MF:	769, de 13/12/2001 DOU 14/12/2001 ()

Modelos:	<p>LCD-15 A 500 (SW 500LC; SW 570LE; SW 570LS); FLATRON L1510S; FLATRON L1511S; FLATRON 563LS; FLATRON 563LE; FLATRON 575MS; FLATRON 568LM; FLATRON 577LM; L1510SL;L1511SL; L1511SK; FLATRON L1720B; FLATRON L1935A; FLATRON L1735A; FLATRON L1740B; FLATRON L1940; L1960TR-BF; L1760TR-BF; L194WT-SF;L196WT-BF; L196WT-WF; L196WT-SF; M198WA-BM; M208WA-BM; M228WA-BM; L1753HM-SF; L1753HR-SF; L1753S-SF; L1753T-SF; L1753TR-SF; L1753H-SF; L1753TR-BF; L1753H-BF; L1753HM-BF; L1753HR-BF; L1753S-BF; L1753T-BF; L1953HM-BF; L1953H-BF; L1953HR-BF; L1953S-BF; L1953TR-BF; L1953T-BF; L1953S-SF; L1953TR-SF; L1953T-SF; L1953HR-SF; L1953HM-SF; L1953H-SF; L194WT-BF; L194WT-SF; L194WTM-BF; L194WTM-SF; L196WTR-BF; L204WT-BF; L204WT-SF; L204WTM-BF; L204WTM-SF; L196WTR-SF; L196WTR-WF; L226WT-SF; L206WT-SF; L206WT-WF; L206WTR-BF; L206WTR-SF; L206WTR-WF; L226WTR-SF; L226WT-BF; L206WT-BF; L226WTR-BF; L226WTM-SF; L226WTM-BF; L226WT-WF; L226WA-SN; L226WA-BN; L226WA-WN; L226WAM-SN; L226WAM-BN; L245WP-BN; L245WP-SN; L245WPM-BN; L245WPM-SN; L246WP-BN; L246WP-SN; L246WPM-BN; L246WPM-SN; L207WH-SF; L207WP-WF; M1921A-BM; M1721A-BM; L1510BF; L1730SFK; L1730SF; L1731SFK; L1731SF; L1954TQ-BF; L1954TQ-SF; L1954TQ-GF; L1954PQ-BF; L1954PQ-SF; L1972H-SF; L1972H-BF; L197WT-SF; L197WT-BF; L207WH-BF; L196WTQ-SF; L196WTQ-BF; L196WTQ-WF; L196WTG-WF; L206WTQ-SF; L206WTQ-BF; L206WTQ-WF; L206WTG-WF; L226WTQ-SF; L226WTQ-BF; L226WTG-WF; L1960TG-BF; L1960TC-BF; L1553S-BF; L1553S-SF; L1760SR-BF; L177WS-PF; L177WSB-PF; L177WSB-BF; L174WS-BF; L174WS-SF; L177WS-BF; L177WS-SF; L226WTQ-PF; W1942T-PF (22/11/07); W1942S-PF (22/11/07); E L1755S-PF; L1755T-PF; L1755T-BF; W1942S-BF; W1752TQ-PF; W1942T-BF; W1952S-PF; W1952TQ-PF; W1942TQ-PF; W1942TQ-BF; W2252TQ-WF; W2252S-WF; W2252S-PF; W2252TQ-PF; W1952T-WF; W1752T-WF; W1952S-WF; W1752T-PF; W1642S-PF; W1752TQ-WF; W1752S-PF; L1755S-BF (22/11/07); L196WSQ-BF; L196WSQ-PF E L196WSQ-SF (20-12-07: W1942SB-PF)(20-12-07: W1952TB-PF)(01-02-08: W1952SB-PF)(01-02-08: M198WA-BM) (23-04-08: W2284T-PF)(23-04-08: L1742S-BF)(23-04-08: L1942P-BF)(23-04-08: L1742P-BF)(23-04-08: W2284F-PF) (15-08-08: L1942S-BF)(15-08-08: W1941S-PF)(15-08-08: W1542S-PF)(15-08-08: W2452T-PF)(15-08-08: W2452V-PF)(15-08-08: W2452S-PF)(18-09-08: L1942S-PF)(18-09-08: L1742T-BF)(02-10-08: W1942SM-BF)(02-10-08: W1971SC-PF)(02-10-08: W1942SM-SF)(02-10-08: L1742P-SF)(02-10-08: W1942SM-PF)(02-10-08: L1742S-SF)(17-10-08: W2271TC-PF)(21-11-08: F8400P-PN)(21-11-08: F8400N-PN)(22-12-08: W1941J-PF)(22-12-08: W2053TQ-PF) (22-12-08: W2043S-PF)(22-12-08: W2353V-PF)(22-12-08: W2053S-PF)(22-12-08: W2254TQ-PF)(22-12-08: W1943S-PF)(22-12-08: W2243T-PF)(22-12-08: W1941J-PS)(22-12-08: W1953T-PF)(22-12-08: W2243S-PF)(22-12-08: W1943C-PF)(22-12-08: W1953S-PF)(22-12-08: W1953C-PF)(22-12-08: W2253S-PF)(22-12-08: W2043T-PF)(22-12-08: W2253TQ-PF)(22-12-08: W1954S-PF)(22-12-08: W2253V-PF)(22-12-08: W1954TQ-PF)(22-12-08: W2386V-PF)(11-02-09: M237WD-PZ)(11-02-09: M4210D-B21)(11-02-09: M4212C-BA)(11-02-09: M4222C-BA)(11-02-09: M4714C-BN)(11-02-09: M4714C-BA)(11-02-09: M237WA-PM)(11-02-09: W2053T-PF)(11-02-09: W2353S-PF)(19-02-09: W1642C-PF)(24-03-09: F7000N-PN)(24-03-09: F7000N-WN)(02-04-09: N1941W-PF)(02-04-09: N1742L-BF) (02-04-09: N1642W-PF)(17-04-09: W2753V-PF)(21-07-09: POSITIVO LINE 701G)(04-08-09: W1953SE-PF)(04-08-09: W1953TE-PF)(18-08-09: N1742LH-BF)(18-08-09: W1943SE-PF)(18-08-09: W2486L-PF)(18-08-09: W1942P-PF)(27-08-09: W2243C-PF)(27-08-09: W1942T-PF) (29/09/2009 L1742PE-BF) (29/09/2009 L1742SE-BF) (29-09-2009: L1742PE-SF) (29-09-2009: L1742TE-BF) (29-09-2009: L1742TE-BF) (29-09-2009: L1742TE-BF) (29-09-2009: L1742TE-BF)(09-12-09: L200B)(09-12-09: L190HB)(09-12-09: L185B)(09-12-09: M197WAP-PM)(09-12-09: M227WAP-PM)(09-12-09: M237WAP-PM)(18-12-09: E2250V-PN)(18-12-09: E2050S-PN)(18-12-09: E2050T-PN)(18-12-09: E2250S-PN)(18-12-09: E2350V-PN)(18-12-09: E1940S-PN)(18-12-09: E1950T-PN)(18-12-09: E1940T-PN) (18-12-09: E2040T-PN)(18-12-09: E2350S-PN)(18-12-09: W1643C-PF)(14-01-10: E2240S-PN)(11-02-10: W1942SE-PF)(11-02-10: W1942TE-PF)(11-02-10: W1942PE-PF)(30-03-10: M4214T-BA)(30-03-10: M4214C-BA)(06-07-10: E2060T-PN)(06-07-10: E2360V-PN)(14-09-10: N1642WC-PF) (15-09-10: N194WHA-BF) (10-11-10: W1943J-E-PF) (29-12-10: E1941S-PN) (29-12-10: E2041S-PN) (29-12-10: E2241S-PN) (04-02-11: W1946P-BF) (04-02-11: IPS236V-PN) (21-02-11: W2046P-BF) (21-02-11: W2046T-BF) (21-02-11: W1946T-BF) (08-04-11: M4720CCBA) (13-04-11: E2260V-PN) (13-04-11: E1960T-PN) (27-05-11: D2342P-PN) (08-07-11: E1641S-PN) (22-07-11: IPS225V-BN) (22-07-11: IPS225V-PN) (02-09-11: E2011P-BN) (02-09-11: L185X) (02-09-11: L200X) (02-09-11: L200HX) (14-09-11: E1960T-BN) (14-09-11: E2060T-BN) (14-09-11: E2360V-BN) (14-09-11: E2260V-BN) (03-10-11: 47WV30-BAA) (24-01-12: 47VL10-BAA) (24-01-12: 47WV30BS-B) (24-01-12: M4210LCBA) (24-01-12: E1941C-PN) (24-01-12: E2241C-PN) (24-01-12: E2241V-PN) (30-03-12: E2355V-PN) (30-04-12: IPS224V-BN) (30-04-12: IPS224V-PN) (30-04-12: E2041C-PN) (02-05-12: E2041T-PN) (02-05-12: 47VL10-BNA) (02-05-12: M4210LCBN) (24-05-12: 47VS20-BAA) (20-07-12: E1641C-PN) (20-07-12: IPS234V-PN) (02-08-12: 47WS10-BAA) (06-08-12: D2343P-BN) (06-08-12: E2241TC-PN) (08-11-12: E1941CP-PN) (08-11-12: 55WV70BS-S) (17-12-12: E2241VP-PN) (06-02-13: 22EA53T-P) (06-02-13: LS1920) (06-02-13: 23EA53T-P) (27-02-13: 23EA53V-P) (11-03-13: 19EB13P-B) (20-03-13: 42WL10MS-B) (20-03-13: 47WL10MS-B) (20-03-13: 42WL10MS-B) (20-03-13: 42WL10MS-B) (20-03-13: 42WS50BS-B) (20-03-13: 47WS50BS-B) (20-03-13: 42WS50BS-B) (20-03-13: 42WS50BS-B) (20-03-13: 47WS50BS-B) (30-04-13: 20EN335S-B) (29-05-13: 84WS70MS-B) (29-05-13: 84WS70BS-B) (05-06-13: 19CNV42K-B) (02-07-13: 29EB73-P) (02-07-13: 29EA73-P) (18-07-13: 19EB13T-B)(17-09-13: V200BZ) (17-09-13: V206HZ) (25-10-13: 47WV50BS-B) (30-12-13: 23MP65HQ-P) (30-12-13: 23MP55HQ-P) (30-12-13: 22MP55HQ-P) (19-02-14: 25UM65-P) (26-05-14: 22MP55PQ-P) (28-05-14: 42LS33A-5D) (28-05-14: 23MB35PH-B) (05-06-14: 47LS33A-5D) (25-06-14: 20M35P-B) (29-07-14: 20M35PD-B)(15-09-14: 20EN335S-M) (15-09-14: 20M35PD-M) (15-09-14: 23MB35VQ-M) (15-09-14: MVD-5521) (15-09-14: 22MP55PQ-B) (15-09-14: 22MP55VQ-B) (15-09-14: 22MP55HQ-B)(13-10-14: 55LV75A-4B) (07-11-14: 47LV35A-3B) (28-11-14: 42LS33A-5B) (28-11-14: 47LV33A-5B) (24-04-15: 55LS73B-5B) (24-04-15: 42LS73B-5B) (24-04-15: 49SE3KB-B) (24-04-15: 49LS73B-5B) (24-04-15: 55LV35A-3B) (06-05-15: 43SE3KB-B) (15-06-15: 29UM67-P) (15-06-15: 25UM57-P) (24-08-15: 20M37AA-B) (26-08-15: 19M37D-B) (01-10-15: 22MP55PY-B)(12-11-15: 43SM5B-B) (12-11-15: 49SM5B-B) (16-12-15: 32SE3B-B) (21-01-16: 23MB35VQ-H) (10-02-16: 49SE3B-B) (10-02-16: 43SE3B-B) (10-02-16: 55SM5KB-B) (10-02-16: 55SE3KB-B) (18-02-16: 16M38A-B) (04-03-16: 20M35PD-D) (18-03-16: 34UM68-P) (18-03-16: 20M35TD-B) (18-03-16: 29UM68-P) (18-03-16: 25UM58-P) (18-03-16: 22MP58VQ-P) (01-06-16: 24MP58VQ-P) (17-06-16: 32SM5B-B) (24-08-16: 43SM5C-B) (24-08-16: 49SM5C-B) (09-09-16: 32SM5C-B) (27-09-16: 23MB35PY-B) (18-10-16: 34UC79G-B) (18-10-16: 22MP55VQ-N) (07-12-16: 29UM69G-P) (07-12-16: 29UB67-B) (07-12-16: 27UD58-B) (07-12-16: 25UB55-B) (03-03-17: 29UM69G-B) (19-04-17: 24M38H-B) (27-04-17: 16M38A-M) (12-05-17: 43SE3KD-B) (12-05-17: 49SE3KD-B) (12-05-17: 55SE3KD-B) (12-05-17: 49SM5D-B) (24-05-17: 43SM5D-B) (30-06-17: 32SM5D-B) (18-08-17: 32SE3D-B) (08-09-17: 49VL5B-X) (20-10-17: 32UD59-B) (26-01-18: 27GK750F-B) (26-01-18: 86BH5C-B) (08-02-18: 65UH5C-B) (22-02-18: 24GM79G-B) (22-02-18: 27UD59-B) (22-02-18: 86UH5C-B) (22-02-18: 29WK600-W) (08-03-18: 75UH5C-B) (23-03-18: 34WK650-W) (10-05-18: 55LV5D-B.AWZ) (18-06-18: 20M37AA-W) (31-07-18: 55LV75D-B) (17-08-18: 49SM5KE-B) (17-08-18: 43SM5KE-B) (30-08-18: 22MK400H-B) (30-08-18: 24MK430H-B) (10-09-18: 55UH5C-B) (05-10-18: 20M35PH-B) (05-10-18: 20M35TH-B) (31-10-18: 22MP55PJ-B) (26-11-18: 43SE3KE-B) (26-11-18: 49SE3KE-B) (26-11-18: 24BL55Q-B) (07-12-18: 55SE3KE-B) (07-12-18: 32SE3KE-B) (14-01-19: 24CAV37K-B) (08-02-19: 32UL750-W) (25-02-19: 24BK550Y-B) (15-03-19: 19M37AA-B) (15-03-19: 24GL600F-B) (15-03-19: 27UL650-W) (15-03-19: 55VM5E-A) (29-03-19: 27UL500-W) (29-03-19: 32SM5KE-B) (23-04-19: 32UK550-B) (23-04-19: 29WK500-P) (02-05-19: 24MK600M-B) (07-05-19: 65UH5E-B) (07-05-19: 24BK550Y-I) (07-05-19: 60UL3E-B) (06-06-19: 70UL3E-T) (13-06-19: 24ML600M-B) (29-08-19: 20MK400H-B) (02-09-19: 27GL650F-B) (02-09-19: 34GL750-B) (05-09-19: 22MK600M-B)</p>
----------	---

Voltar